

CLERMONT HISTORIC STRUCTURE REPORT
TABLE OF CONTENTS

ACKNOWLEDGMENTS

EXECUTIVE SUMMARY

CHAPTER 1: INTRODUCTION

A. Clermont Property Ownership and Management	1.1
B. Purpose of Historic Structure Report.....	1.2
C. Historic Preservation Objectives	1.4
D. Methods of Evaluation.....	1.5
E. Location of Property	1.7
F. Recommendations For Further Study	1.9
G. Site Interventions Time Line (2005-2012) Prior to Completion of the HSR	1.11

CHAPTER 2: DEVELOPMENTAL HISTORY

A. Historical Background and Context.....	2.1
B. John Vance and Thomas Wadlington Ownership (1750-1770)	2.1
C. Edward Snickers and William Snickers Ownership (1770-1819).....	2.8
D. Dawson McCormick Ownership (1819-1847).....	2.14
E. Edward McCormick Ownership (1848-1870).....	2.17
F. Ellen Lane Jett McCormick Ownership (1870-1908).....	2.19
G. Dr. A. M. Dupuy McCormick and His Heirs Ownership (1910-1958)	2.22
H. Edward McCormick Williams and Elizabeth Rust Williams Ownership (1958-2004).....	2.25

CHAPTER 3: CLERMONT CHAIN OF KEY EVENTS 1750-2012..... 3.1

CHAPTER 4: PROPERTY DESCRIPTION

A. Synopsis	4.1
B. Main House	4.1
1. East Frame	4.12
2. West Frame.....	4.24
3. Stone Section	4.32
4. Western Wing	4.35
5. 1971 Section	4.39
C. Slave Quarters	4.46
D. Smokehouse	4.53
E. Garage and Machine Shop	4.55
F. Two Archaeological Sites near Main House	4.56
G. Site of Cemetery	4.57
H. Springhouse.....	4.58
I. Barn Foundation	4.60
J. Main Barn	4.61
K. Cornhouse	4.62
L. Tenant House #1.....	4.64
M. Log Shed near Tenant House #1	4.65
N. Frame Shed near Tenant House #1	4.66
O. Turn-Out Shed near Tenant House #1	4.66
P. Machine Shed.....	4.66
Q. Tenant House #2.....	4.67
R. Sheds at Tenant House #2	4.68

CHAPTER 5: ARCHITECTURAL DEVELOPMENT

A. Introduction.....	5.1
B. Period 1 (1756-1776).....	5.5
C. Period 2 (1777-1822).....	5.22
D. Period 3 (1823-1848).....	5.61
E. Period 4 (1849-1870).....	5.68
F. Period 5 (1871-1945).....	5.76
G. Period 6 (1946-2004).....	5.79

CHAPTER 6: ARCHITECTURAL CODE ANALYSIS

A. Code Requirements and Accessibility Issues.....	6.1
Accessibility Issues	6.2
Fire Safety.....	6.4
Plumbing.....	6.8
Heating, Air-Conditioning, and Electrical	6.9

CHAPTER 7: PROPERTY ASSESSMENT AND RECOMMENDATIONS FOR PRESERVATION

A. Introduction and Objective.....	7.1
B. Architectural Condition Assessment and Treatment Plan.....	7.2
C. Structural Floor System Assessment – Live Load Ratings	7.29
D. Building Systems.....	7.33
1. Heating and Air Conditioning.....	7.33
2. Plumbing Systems	7.42
3. Electrical System	7.47
E. Environmental Testing and Recommendations	7.52

CHAPTER 8: PROGRAM CONSIDERATIONS

A. Space Use.....	8.1
B. Accessibility Plan	8.2

CHAPTER 9: ABOUT THE PRINCIPAL TEAM MEMBERS.....9.1

APPENDICES:

A. Annotated Bibliography	
B. Location of Photos for Chapter 4	
C. Existing Conditions Drawings	
D. Conjectural Drawings by Period 1-6	
E. Interior Existing Moldings and Woodwork Drawings	
F. Exterior Existing Moldings and Woodwork Drawings	
G. Framing, Flooring, Door, and Hardware Schedules	
H. Historic Photo Images	
I. Paint Analysis Report	
J. Dendrochronology Report	
K. Historic Construction Drawings	
L. Clermont Archaeological Survey Plan	
M. Shoe Report	
N. Structural Existing Condition Floor Plans	
O. Summary of Building Dates Related to Ownership Chronology	